



INSTALLATION INSTRUCTIONS:

1. PREPARE PANEL AS SHOWN. TOP EDGE OF
HOLE SHOULD BE SHARP. RECOMMENDED MIN.
DISTANCE FROM EDGE OF PANEL TO THE
CENTERLINE OF THE HOLE IS .47.

- 2. PLACE FERRULE INTO INSTALLATION HOLE.
- 3. PROVIDE A SOLID BACK-UP SURFACE BEHIND THE PANEL WITH A CLEARANCE HOLE OF Ø.146 : 80% FOR THE SCREW.
- 4. PRESS THE KNURL INTO PANEL UNTIL ONLY THE TOP OF THE KNURL ON THE FERRULE IS VISIBLE.
- 5. HAND TIGHTEN FIRMLY TO ENGAGE THE RATCHET MECHANISM.





UNFASTENED SCREW RETRACTED




PANEL PREPARATION

SCREW RECESS STYLES









FASTENED